

Interim Certificate of Class

9431769
IMO-No.

113067
GL-Register-No.

This is to certify that the Motor Ship

" APL SRI LANKA "

Flag	Antigua and Barbuda	Call Sign	V2EC8
Port of Registry	St. John's		
Owner	MS "BERNHARD-S." GmbH & Co. KG		
Shipyard	Jiangsu New Yangzijiang Shipbuilding Co., Ltd.		
Place of Build	Jiangyin		
Completion	2010-05-20		

has been surveyed at **Jiangyin, China**
on **2010-05-20** by our Surveyor(s) in accordance with this Society's Rules.

for the purpose of assigning the class:

Hull	<input checked="" type="checkbox"/> 100 A5 with freeboard 3.796 m IW NAV-O RSD SOLAS-II-2, Reg.19 Container Ship
Machinery	<input checked="" type="checkbox"/> MC AUT



Period of Class running from **20th May 2010**

This certificate is valid until receipt of the final class certificate to be issued by Head Office of Germanischer Lloyd but no longer than **19th October 2010**

With this certificate the preliminary granting of class is confirmed until the issue of the relevant class certificate has been effected.

Germanischer Lloyd

Jiangyin, 20th May 2010


GL Representative(s) **SARIGUL**  Stamp
(Zhu Shuguang, Su Jianhong)

GL 

The latest edition of the General Terms and Conditions of Germanischer Lloyd is applicable (see Chap. I-Ship Technology, Part 0-Classification and Surveys).
Germanischer Lloyd Aktiengesellschaft, Registered Office Hamburg, HR B 31393

9431769
IMO-No.

113067
GL-Register-No.

Additional Information to Interim Certificate of Class

no Ice Class

Remarks

no remarks


GL Representative(s)
(Zhu Shuguang, Su Jianhong)


Stamp

- IMPORTANT CLASS REQUIREMENTS -

- According to procedures agreed within IACS the class will automatically be suspended
- by the due date, if surveys towards Class Renewal have not been completed or are not in progress
 - 3 months after their due date, if the Annual or Intermediate Surveys are not completed
 - by the assigned due date, if a Condition of Class is not dealt with

Any suspension of class will have to be reported to the vessel's competent Flag State Authority and the IACS Permanent Secretariat.